


Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



**Location Overview: Location is within High Priority/Density
Habitat areas. Location is approximately 27 yards from a
drainage that contributes to the Colorado River.
Section/Township/Range: 19 6S94W**

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RMV 63-19 Pad
Location #: 335176



Photo # 8159 Insufficient BMP's at entrance to location /sediment laden stormwater migrating from lease road onto location

Photo # 8160 Insufficient BMP's at entrance to location /sediment laden stormwater migrating from lease road onto location