

State of Colorado  
Energy & Carbon Management Commission



Document Number:  
403985767

Date Received:  
11/06/2024

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 83130  
Name of Operator: STRACHAN EXPLORATION INC

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

#### Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Costa, Ryan

ryan.costa@state.co.us

Harms, Jason

Jason@strachanexploration.com

L. Stacy

stacy@strachanexploration.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 710500377

Inspection Date: 09/24/2024

FIR Submit Date: 09/26/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: STRACHAN EXPLORATION INC

Company Number: 83130

Address: 992 S 4TH AVE SUITE 100-461

City: BRIGHTON State: CO Zip: 80601

#### LOCATION - Location ID: 321213

Location Name: BOURNE-622S48W Number: 30SENW County: \_\_\_\_\_

Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6

Latitude: 38.108555 Longitude: -102.844724

#### FACILITY - API Number: 05-011- -00 Facility ID: 321213

Facility Name: BOURNE-622S48W Number: 30SENW

Qtrqtr: SENW Sec: 30 Twp: 22S Range: 48W Meridian: 6

Latitude: 38.108555 Longitude: -102.844724

### CORRECTIVE ACTIONS:

1 CA# 199075

Corrective Action: Original corrective action Date shall apply

Date: 09/25/2024

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator  
Comment: Sign Installed

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 199076

Corrective Action: Install sign to comply with Rule 605.e

Date: 09/25/2024

Original Corrective action date shall apply

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator  
Comment: Sign installed

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**3** CA# 199077

Corrective Action: Dispose of contaminates soils in accordance with Rule 905. Operator shall provide waste manifest once contaminated soils are removed

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 10/04/2024

Operator  
Comment: Buckets of impacted soil delivered to Otero Landfill Manifest included in attachments - secondary containment removed from location

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**4** CA# 199078

Corrective Action: Comply with Rule 606.

Date: 09/25/2024

Original CA date shall apply

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator  
Comment: risers capped and marked

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**5** CA# 199079

Corrective Action: Comply with 606.  
Original Corrective action date shall apply

Date: 09/25/2024

Response: CA COMPLETED

Date of Completion: 09/25/2024

Operator  
Comment: Weeds mowed on perimeter and the few inside the perimeter were also mowed. Rebuild of berm unnecessary as tank was removed under F27 for decommissioning.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Mowed, capped stubs, removed impacted soil, replaced sign w proper operator, Removed MEOH tank and secondary containment (stocktank)

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Shawn Reed

Signed:

Title: Petroleum Consultant

Date: 11/6/2024 10:22:00 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

403985769	Manifest at Otero Landfill for impacted soil
-----------	--

Total Attach: 1 Files