

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad
Location ID: 311663



**Location Overview: Location is within High Priority/Density
Habitat areas & in close proximity to NSO Habitat area.
Location is approximately 15 yards from a creek that
contributes to the Colorado River.
Section/Township/Range: 9 6S94W**



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad
Location ID: 311663



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC FEDERAL RWF 324-9 Pad
Location ID: 311663



Photo # 9503 Failure to maintain chemical BMP - Chemical tank containment full of fluid/BMP insufficient to contain possible spill.



Photo # 9504 Failure to maintain chemical BMP - Chemical tank containment full of fluid/BMP insufficient to contain possible spill. (Additionally the standing fluid on top of chemical tank containment is also a wildlife hazard)