

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/07/2024

Submitted Date:

11/07/2024

Document Number:

717700643**FIELD INSPECTION FORM**Loc ID 458676 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10518Name of Operator: CONFLUENCE DJ LLCAddress: 1401 WYNKOOP STREET STE 120City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Gale, Justin		jpgale@confluencelp.com	All Inspections
Rothe, Brittany		brothe@confluencelp.com	All Inspections
,		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
458680	WELL	DG	03/03/2020	LO	123-48439	Silverton 5-2-4L-DNU	DG

General Comment:[This is an audit on the well](#)

Location

Overall Good: ☒

Emergency Contact Number:

Comment: Well doesnt have a well sign

Corrective Action:

Date:

Overall Good: ☐

Spills:

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 458680 Type: WELL API Number: 123-48439 Status: DG Insp. Status: DG**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____

Comment: T/A, Surface casing has been drilled. Form 5 received on 4/23/2020
Confluence has suspended drilling operations in order to evaluate the economic viability of horizontal development in this area prior to continuing the Silverton program. The anticipated date of resumption of drilling is TBD pending the results of Confluence's economic analysis. Confluence will comply with all bradenhead and MIT testing requirements during the suspension of operations.

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____
End Surf Csg Pressure: _____Comment: No updated annual BH test on file. 12/20/2024Corrective Action: Submit reports as per Rule 419. Date: _____

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments

Comment	User	Date
ECMC Inspection Report Summary On Tuesday, November 5, 2024, at approximately 10:47 AM, Inspector Adam Burns conducted an on-site inspection at the following location: Well: Silverton 5-2-4L-DNU Operator: Confluence DJ LLC API #05-123-48439 County: Weld During the inspection, a producing well was observed. The following possible compliance issues were identified: No updated annual BH test on file. Submit reports as per Rule 419. A follow-up inspection is scheduled to ensure that the compliance issues have been rectified to comply with ECMC rules. Please note that any corrective actions from previous inspections that have not been addressed remain applicable.	burnsa	11/07/2024

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403986852	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6777892
717700644	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6777852