

**Andrea Gross**

---


**From:** dylan cohoon <dylancohoon@gmail.com>  
**Sent:** Friday, October 25, 2024 7:59 PM  
**To:** Meghan Grimes  
**Subject:** [EXTERNAL] CA3 (pics 10-15) part 1



Caution: This email originated from outside your organization. Use caution when opening attachments or clicking on embedded links. Please report any suspicious requests or activity.







The pilot Thomas tanks nets were saturated in oil which needed to be changed with new clean wire also inside the tanks had a motor oil water combo in them which I also had sucked out also cleaned and removed all contaminated soil around the tanks















We had a Workover rig on location at the time of inspection as you can see the rig has since moved on the problem pics was coming from the pump skid that needed its packing changed and it was leaking production water and the problem was corrected same day it was found the pics above are the area where the pump skid was and where the rig itself was

Sent from my iPhone