

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403996205

Date Received:
11/15/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10518

Name of Operator: CONFLUENCE DJ LLC

Address: 1401 WYNKOOP STREET STE 120

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Justin Gale

igale@confluencelp.com

Brittany Grasmick

bgrasmick@confluencelp.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 717700635

Inspection Date: 11/06/2024

FIR Submit Date: 11/07/2024

FIR Status: _____

Inspected Operator Information:

Company Name: CONFLUENCE DJ LLC

Company Number: 10518

Address: 1401 WYNKOOP STREET STE 120

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 458676

Location Name: Silverton Number: 4 North County: _____

Qtrqtr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.341000 Longitude: -104.449700

FACILITY - API Number: 05-123-00 Facility ID: 481826

Facility Name: Silverton 4 North Tank Battery Number: _____

Qtrqtr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6

Latitude: 40.341000 Longitude: -104.449700

CORRECTIVE ACTIONS:

1 CA# 200305

Corrective Action: Install sign to comply with Rule 605.h.

Date: 12/31/2024

Response: CA COMPLETED

Date of Completion: 11/15/2024

Operator Comment: This corrective action is not yet completed, but a response is required to submit the form. Will follow up on this corrective action when proper signage is in place and prior to 12/31/24 due date.

ECMC Decision: _____

ECMC
Representative:

2 CA# 200306

Corrective Action: "Properly dispose of oily waste in accordance with 905.e."

Date: 11/15/2024

Response: CA COMPLETED

Date of Completion: 11/13/2024

Operator
Comment:

All soil with oil residue near the Silverton 4 North gas lift compressor was removed and properly disposed of on 11/13/2024. Please refer to attached photo.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: One of two corrective actions has been addressed on this FIRR. Follow-up FIRR forthcoming when second corrective action is completed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brittany Grasmick

Signed: _____

Title: Engineering Manager

Date: 11/15/2024 10:19:20 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403996205	FIR RESOLUTION SUBMITTED
403996218	2024-11-13 CA 200306_Insp 717700635_Soil Cleaned

Total Attach: 2 Files