

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403998109

Date Received:
11/18/2024

FIR RESOLUTION FORM

Overall Status:

CA Summary:
1 of 1 CAs from the FIR responded to on this Form
1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10518
Name of Operator: CONFLUENCE DJ LLC
Address: 1401 WYNKOOP STREET STE 120
City: DENVER State: CO Zip: 80202
Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
<u>Brittany Grasmick</u>		<u>bgrammick@confluencelp.com</u>
<u>Justin Gale</u>		<u>jpgale@confluencelp.com</u>
-		<u>dnr_cogccengineering@state.co.us</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 717700645
Inspection Date: 11/07/2024 FIR Submit Date: 11/07/2024 FIR Status:

Inspected Operator Information:

Company Name: CONFLUENCE DJ LLC Company Number: 10518
Address: 1401 WYNKOOP STREET STE 120
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 458676

Location Name: Silverton Number: 4 North County: WELD
Qtrqtr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W
Latitude: 40.341460 Longitude: -104.451510

FACILITY - API Number: 05-123-00 Facility ID: 458679

Facility Name: SILVERTON Number: 5-4-3L
Qtrqtr: SWN Sec: 4 Twp: 4N Range: 63W Meridian: 6
W
Latitude: 40.341460 Longitude: -104.451510

CORRECTIVE ACTIONS:

1 CA# 200300

Corrective Action: Submit reports as per Rule 419. Date: 12/20/2024
Response: CA COMPLETED Date of Completion: 11/18/2024

The subject wellbore only has 9-5/8" 36# J-55 surface casing set to a depth of ~1,550'. The surface casing has been cemented back to surface with excess cement and has never been drilled out. Therefore, there's no

Operator Comment: annulus to test for pressure from a deeper-set string of casing set in hydrocarbon-bearing formations and no cause to MIT the wellbore that is isolated surface casing only.
Confluence's Form 5 submittal was confusing because we stated that 'Confluence will comply with all bradenhead and MIT testing requirements during the suspension of operations.' That was an error on our part.

ECMC Decision: _____

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please find attached a picture of the subject well's well sign. This had been stored in the well's cellar while offset wells' hydraulic fracturing operations were taking place. Confluence will order a clean, new sign for the subject well.
Please let me know if there are any further questions.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Brittany Grasmick Signed: _____

Title: Engineering Manager Date: 11/18/2024 1:33:05 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403998115	Silverton 5-4-3L Well Sign

Total Attach: 1 Files