

Craig 2

Location 327437

Photo Log

Corrective Action:	Repair or install berms or other secondary containment devices per Rule 603.o.
Description:	Berm has been repaired.





Comment:	Skim Tank at Pits missing NFPA, Content and Capacity Labels
Description:	NFPA has been replaced



