

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404022585

Date Received:  
12/10/2024

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

ERIN JOSEPH

970-515-1169

ECMCInspections@Oxy.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 714300146

Inspection Date: 11/14/2024

FIR Submit Date: 11/19/2024

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

#### LOCATION - Location ID: 336059

Location Name: RASMUSSEN Number: 39-29 County: \_\_\_\_\_

Qtrqtr: SWSE Sec: 29 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.104328 Longitude: -105.024735

#### FACILITY - API Number: 05-123- -00 Facility ID: 488174

Facility Name: Rasmussen 39-29 Wellhead Number: \_\_\_\_\_

Qtrqtr: SWSE Sec: 29 Twp: 2N Range: 68W Meridian: 6

Latitude: 40.104328 Longitude: -105.024735

### CORRECTIVE ACTIONS:

1 CA# 200539

Corrective Action: Secure access to excavation in compliance with Rule 913.b.(5).B.i and ECMC Guidance 913.b.(5)B i-v

Date: 12/03/2024

Response: CA COMPLETED

Date of Completion: 11/25/2024

Operator  
Comment:

The snow fencing was fixed around the Rasmussen 39-29 Wellhead excavation on 11/25/24.

ECMC Decision: \_\_\_\_\_

ECMC Representative:			
<b>2</b>	<b>CA# 200540</b>		
Corrective Action:	If soil is to be stockpiled on location Operator shall install a sign to denote if the stockpile is clean or contaminated. If soil stockpile is contaminated Operator will collect a soil sample from underneath the observed soil stockpile area prior to spill closure. Install or repair required BMPs per Rule 1002.f.(2)C.		Date: <u>12/03/2024</u>
Response:	CA COMPLETED		Date of Completion: <u>11/27/2024</u>
Operator Comment:	Soil stockpiles were removed from the Rasmussen 39-29 Wellhead excavation area on 11/25/24. Soil samples were collected from underneath the observed soil stockpile area on 11/27/24.		
ECMC Decision:			
ECMC Representative:			

<b>OPERATOR COMMENT AND SUBMITTAL</b>	
Comment:	
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: <u>ERIN JOSEPH</u>	Signed: _____
Title: <u>SR REGULATORY ADVISOR</u>	Date: <u>12/10/2024 2:34:07 PM</u>

## ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404022585	FIR RESOLUTION SUBMITTED
404022639	LOCATION PHOTOS

Total Attach: 2 Files