

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404050245

Date Received:

01/07/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10684

Name of Operator: EPIC ENERGY LLC

Address: 332 RD 3100

City: AZTEC State: NM Zip: 87410

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Arleen Smith

Phone

5053274892

Email

arleen@walsheng.net

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001260

Inspection Date: 09/18/2024

FIR Submit Date: 09/24/2024

FIR Status: _____

Inspected Operator Information:

Company Name: EPIC ENERGY LLC

Company Number: 10684

Address: 332 RD 3100

City: AZTEC State: NM Zip: 87410

LOCATION - Location ID: 378705

Location Name: TINKER-N34N1W Number: 14NENE County: _____

Qtrqtr: NENE Sec: 14 Twp: 34N Range: 1W Meridian: N

Latitude: 37.190372 Longitude: -106.913750

FACILITY - API Number: 05-007- -00 Facility ID: 378705

Facility Name: TINKER-N34N1W Number: 14NENE

Qtrqtr: NENE Sec: 14 Twp: 34N Range: 1W Meridian: N

Latitude: 37.190372 Longitude: -106.913750

CORRECTIVE ACTIONS:

1 CA# 198988

Corrective Action: Comply with Rule 1004. Reseed access road areas using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1004 standards, including stormwater and weed management.

Date: 10/09/2024

Response: CA COMPLETED

Date of Completion: 10/09/2024

Operator
Comment:

Seeded access road with Pinyon Juniper seed mix.

ECMC Decision: _____

ECMC
Representative: _____

2 CA# 198989

Corrective Action: Install or repair required BMPs. Continue to manage stormwater until access road is stabilized with long term desirable vegetation.

Date: 10/08/2024

Response: CA COMPLETED

Date of Completion: 10/08/2024

Operator
Comment:

Rerouted the water to drain properly, utilized rock to slow water down, filled in erosion and installed water bars.

ECMC Decision: _____

ECMC
Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: _____

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Arleen Smith

Signed: _____

Title: Regulatory

Date: 1/7/2025 11:55:22 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

| | |
|-----------|--------------------------|
| 404050270 | Corrective Action Photos |
|-----------|--------------------------|

Total Attach: 1 Files