


**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



**Photo # 7598 From entrance to location**



**Photo # 7599 Location**

**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



Jan 8, 2025 at 3:32:21 PM  
CO

**Photo # 7600 Location**




Jan 8, 2025 at 3:33:34 PM  
CO

**Photo # 7601 Location**



**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



**Photo # 7602 Location**




**Photo # 7603 Location**

**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



**Photo # 7604 Location**



**Photo # 7605 Location**



**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



**Photo # 7606 Debris**



**Photo # 7607 Staining & debris**



**Inspection Photos**  
**Location Name: QB Energy Rose 22-9C (K22W) Pad**  
**Location # 433706**



**Photo # 7608 Hole in liner/liner needs maintenance**



**Photo # 7609 Hole in liner/liner needs maintenance**

## Inspection Photos

Location Name: QB Energy Rose 22-9C (K22W) Pad

Location # 433706




Photo # 7610 Tank label contains inaccurate information

