

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2025

Submitted Date:

01/13/2025

Document Number:

715501148

FIELD INSPECTION FORMLoc ID 316279 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10775

Name of Operator: KT RESOURCES LLC

Address: 3381 WESTBROOK LANE

City: HIGHLANDS State: CO Zip: 80129

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

5 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	
Enforcement, ECMC		dnr_cogccenforcement@state.co.us	
Gale, Tony	(303) 886-8733	tony@kt-res.com	
Adams, Karen	(303) 886-8733	adams@kt-res.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260294	WELL	SI	03/01/2024	GW	103-10143	WRD FEDERAL 19-31	SI

General Comment:**ECMC Inspection Report Summary**

On Monday, 01/13/2024, Inspector Kirby Burchett, conducted a follow up inspection at KT Resources LLC on the WRD Federal 19-31 well, Location #316279, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Parks and Wildlife (CPW) District and Black Bear area with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

Follow up inspection in response to compliance issues observed during Insp. #715500496 on 7/31/24 and 3 previous inspections dating back to 4/13/23. The following Corrective Actions are unresolved and original due dates remain:

1. Sediment migration and erosion migration from location.
2. Oily waste and stained soil inside tank battery.
3. Gas meter calibration out of compliance.
4. Weeds.
5. Illegible labels.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐**Signs/Marker:**

Type	CONTAINERS		
Comment:	Faded and illegible labels		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	08/11/2024
Type	WELLHEAD		
Comment:	As Wellhead signs are replaced: The Well name; The API Number; and Its legal location, including the quarter/quarter section will be required.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: (800) 288-0560

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Oil and Gas Locations will be kept free of all Undesirable Plant Species.		
Corrective Action:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.	Date:	08/08/2024

Overall Good: ☐**Spills:**

Type	Area	Volume		
Crude Oil	Tank			
Comment:	Oil inside containment.			
Corrective Action:	Remove and properly dispose of oily waste and impacted soil.	Date:	04/04/2024	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 1		
Comment:	Chemical tanks on containments		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Gas meter calibration out of compliance.		
Corrective Action:	Meters will be calibrated annually unless more frequent calibration is required by contractual obligations or by the Director.		Date: 03/03/2024
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate					
Comment:	Unlined					
Corrective Action:						
			Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	300 BBLS	STEEL AST		,	

Comment:					
Corrective Action:					Date: <input type="text"/>
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate				
Comment:	Unlined				
Corrective Action:					Date: <input type="text"/>
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date: <input type="text"/>
Flaring:					
Type					
Comment:					
Corrective Action:					Date: <input type="text"/>

Inspected Facilities									
Facility ID:	260294	Type:	WELL	API Number:	103-10143	Status:	SI	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <div>Shut In - March 2024 November 2024 Production Report</div>									
Corrective Action: _____ Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches				
Ditches						
Gradient Terraces						
				Material Handling And Spill Prevention		
		Culverts				

Comment: 1. No BMP's installed to prevent sediment migration from occurring on location.
 2. Sediment migration and erosion from location.
 3. Access road and location show signs of lack of staibilization.

Corrective Action: **Install or repair required BMP's**

Date: 05/29/2023

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501149	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6874393