



Two open excavations with fencing observed.




Flowline risers and snow accumulation observed within southern excavation.








Gray staining observed within northern excavation.





Gray staining observed within northern excavation.





Unmarked soil stockpiled on location with inadequate BMPs.

