

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Location Overview – Photo #06195



Location – Photo #06196

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Jan 28, 2025 at 13:36:12  
Silt CO 81652  
United States



Jan 28, 2025 at 13:43:00  
Silt CO 81652  
United States

Location – Photo #06197

Location – Photo #06215

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Location – Photo #06201



Stored Supplies/Wildlife Entry Hazard – Photo #06209

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Stored Supplies/Wildlife Entry Hazard – Photo #06210



Stored Supplies/Wildlife Entry Hazard – Photo #06211

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Stained Soil – Photo #06199



Stained Soil – Photo #06198

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



**Rill Erosion Undercutting BMP – Photo #06202**




**Rill Erosion Undercutting BMP – Photo #06203**

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Jan 28, 2025 at 13:40:47  
Silt CO 81652  
United States



Jan 28, 2025 at 13:42:16  
Silt CO 81652  
United States

Illegible Tank Label – Photo #06207

Staining on Tank – Photo #06213

# Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC, PORTER FEDERAL-66S92W/29SESE

Location ID: 335118

Date: 1/28/2025



Staining on Tank – Photo #06212

Staining on Tank – Photo #06214