

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/04/2025

Submitted Date:

02/04/2025

Document Number:

715501225**FIELD INSPECTION FORM**Loc ID: 316359 Inspector Name: Burchett, Kirby On-Site Inspection: ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	(970) 285-9377	COGCCInspectionReports@terraep.com	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269111	WELL	PR	09/14/2007	GW	103-10363	FEDERAL 298-18-1	PR

General Comment:**ECMC Inspection Report Summary**

On Tuesday, 02/04/2025, Inspector Kirby Burchett, conducted a routine field inspection at TEP Rocky Mountain LLC on the Federal 298-18-1 well, Location #316359, in Rio Blanco County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District, Wildlife Management Plan, and Black Bear area with High Priority, NSO, and Density Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Damaged production tank label.
2. Illegible chemical tank label.
3. Tank heater stack open to wildlife.

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Damaged tank label		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	02/15/2025
Type	CONTAINERS		
Comment:	Faded and illegible label		
Corrective Action:	Operators will ensure that container and tank labels are well maintained and legible, and will replace damaged or vandalized labels within 10 days of discovery that the label is no longer legible or is damaged.	Date:	02/15/2025
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Separator units include attached storage tanks. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-285-9377

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Fence panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Fence panels		

Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Corral panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	Bird protector off Produced Water tank on the ground		
Corrective Action:	All stacks, vents, or other openings will be equipped with screens or other appropriate equipment to prevent entry by wildlife, including birds and bats.	Date:	02/15/2025
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:	Surface and Intermediate casing		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical tank on containment		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	HEATED STEEL AST		,
Comment:	Damaged label. Missing bird protection.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate				
Comment:	Unlined				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS

CONDENSATE	1	OTHER	HEATED STEEL AST		,		
Comment:							
Corrective Action:							Date:
<u>Paint</u>							
Condition	Adequate						
Other (Content)							
Other (Capacity)		210					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate						
Comment:		Unlined					
Corrective Action:							Date:
<u>Venting:</u>							
Yes/No	NO						
Comment:							
Corrective Action:							Date:
<u>Flaring:</u>							
Type							
Comment:							
Corrective Action:							Date:

Inspected Facilities									
Facility ID:	269111	Type:	WELL	API Number:	103-10363	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	November 2024 Production Report								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Berms						
		Drains				
				Material Handling And Spill Prevention		
		Ditches				

Comment: Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501226	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6905283