

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/03/2025

Submitted Date:

02/05/2025

Document Number:

711901827**FIELD INSPECTION FORM**Loc ID 313758 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 10657Name of Operator: PCR OPERATING LLCAddress: 9211 BROADWAY ST #17493City: SAN ANTONIO State: TX Zip: 78217**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		sperson@passcreekresource s.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
225070	WELL	SI	07/29/2015	ERIW	087-05464	Davis, R.Y. 4	SI

General Comment:

FOLLOW-UP FIR – CONDITIONS AT LOCATION REMAIN NON-COMPLIANT – SURFACE MAINTANENCE SHOWS NO INDICATION OF OPERATOR INVOLVEMENT – ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD – LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS – FACILITY BUILDINGS ARE IN DISREPAIR – WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED – FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED.

NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES.

Inspected Facilities

Facility ID: 225070

Type: WELL

API Number: 087-05464

Status: SI

Insp. Status: SI

Idle Well

Purpose: ☒ Shut In

☐ Temporarily Abandoned

Reminder:

Comment:

Corrective Action:

Date:

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

ECMC Comments		
Comment	User	Date
<div>FOLLOW-UP FIR – CONDITIONS AT LOCATION REMAIN NON-COMPLIANT – SURFACE MAINTANENCE SHOWS NO INDICATION OF OPERATOR INVOLVEMENT – ELECTRICAL SERVICE PROVIDED BY XCEL ENERGY HAS BEEN DISCONNECTED TO ENTIRE ADENA FIELD – LANDOWNER/MINERAL OWNER EXPRESSED THAT LEASES HAVE EXPIRED- LOCATION SHOWS NO HOUSEKEEPING IN THE PAST (2-3) YEARS – FACILITY BUILDINGS ARE IN DISREPAIR – WINDOWS ALL BROKEN OUT, DOORS LEFT OPEN OR UNSECURED – FIELD OBSERVATIONS INDICATE THE ADENA FIELD HAS BEEN ABANDONED. NOTE TO OPERATOR: CONTACT ECMC ENFORCEMENT GROUP & ENGINEERING GROUP FOR RESOLUTION DIRECTIVES.</div>	schureky	02/05/2025