

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/28/2025

Submitted Date:

01/30/2025

Document Number:

713601831**FIELD INSPECTION FORM**Loc ID 321605 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION  
☒ FOLLOW UP INSPECTION REQUIRED  
☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Storts, Doug		pds@willifordenergy.com	
GROWNS LARRY		lgrowns@willifordenergy.com	

**General Comment:**

This is a follow up reclamation inspection of the RHOADES Unit Tract 3 #1 wellsite.  
See attached photos and additional details within this report

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	The well sign has been updated.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

**Good Housekeeping:**

Type	DEBRIS		
Comment:	There is a black barrel that has blown offsite into the adjacent pasture.		
Corrective Action:	Comply with Rule 606 to remove the barrel.	Date:	02/06/2025

Overall Good: ☐**Spills:**

Type	Area	Volume		
Condensate	WELLHEAD			
Comment:	Previous inspection noted "There is oil stained soil at the wellhead that must be cleaned up." There are oil stained soils that remain at the wellhead and it appears an additional leak has since occurred. There are now stained soils approximatley 60 ft. east of the wellhead.			
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.			Date:

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	OTHER		
Comment:	The fence around the solar panels has been repaired.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		There are areas of access road which are not stabilized or maintained. There are areas where stormwater is pooling and vehicles are driving around the impacted road causing unnecessary disturbance. The access road needs to be repaired and maintained with BMP's such as road base and culverts. Previous corrective action was not completed.				
Corrective Action:		Install or repair required BMPs per Rule 1002.f.(2)				Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404076165	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6898850">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6898850</a>
713601832	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6898834">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6898834</a>