

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404085911

Date Received:
02/07/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10133
Name of Operator: HILCORP ENERGY COMPANY
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Walker, Mandi</u>		<u>mwalker@hilcorp.com</u>
<u>Shorty, Priscilla</u>	<u>505-324-5188</u>	<u>pshorty@hilcorp.com</u>
<u>.General</u>		<u>FarmingtonRegulatoryTechs@hilcorp.com</u>

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001706
Inspection Date: 01/14/2025 FIR Submit Date: 01/23/2025 FIR Status: _____

Inspected Operator Information:

Company Name: HILCORP ENERGY COMPANY Company Number: 10133
Address: P O BOX 61229
City: HOUSTON State: TX Zip: 77208

LOCATION - Location ID: 326147

Location Name: HUBER-LOBATO-N35N8W Number: 26SEnw County: _____
Qtrqtr: SEnw Sec: 26 Twp: 35N Range: 8W Meridian: N
Latitude: 37.275446 Longitude: -107.716475

FACILITY - API Number: 05-067-00 Facility ID: 326147

Facility Name: HUBER-LOBATO-N35N8W Number: 26SEnw
Qtrqtr: SEnw Sec: 26 Twp: 35N Range: 8W Meridian: N
Latitude: 37.275446 Longitude: -107.716475

CORRECTIVE ACTIONS:

1 CA# 201956

Corrective Action: Maintain equipment and clean up impacted material and dispose per Rule 1002. Date: _____

Response: CA COMPLETED Date of Completion: 02/07/2025

Operator Comment: Impacted soil has been removed and disposed of properly and leaks have been addressed.

ECMC Decision: _____

ECMC Representative: _____

2 CA# 201957

Corrective Action: Comply with rule 606, remove and properly dispose of trash.

Date: 01/30/2025

Response: CA COMPLETED

Date of Completion: 02/07/2025

Operator Comment: Trash has been removed and disposed of properly.

ECMC Decision: _____

ECMC Representative: _____

3 CA# 201958

Corrective Action: Comply with rule 1002.e. and restrict vehicle travel to the access road to avoid damage to interim reclamation areas and vegetation. Repair and conduct reclamation on disturbed areas. ; Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of pre-disturbance or reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local soil conservation district. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until Final Reclamation has passed.

Date: 05/15/2025

Response: CA COMPLETED

Date of Completion: 02/07/2025

Operator Comment: Area has been reseeded and restricted to vehicle access.

ECMC Decision: _____

ECMC Representative: _____

OPERATOR COMMENT AND SUBMITTAL

Comment: See attached RESOLVED Photos.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tammy Jones

Signed: _____

Title: Ops/Regulatory Tech

Date: 2/7/2025 9:51:49 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
404085911	FIR RESOLUTION SUBMITTED
404085933	Resolved Photos

Total Attach: 2 Files