

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/27/2025

Submitted Date:

02/07/2025

Document Number:

701104143**FIELD INSPECTION FORM**Loc ID 476172 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 96730Name of Operator: WILLIFORD ENERGY COMPANYAddress: 6060 AMERICAN PLAZA SUITE 760City: TULSA State: OK Zip: 74135**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Larry Growns		lgrowns@willifordenergy.com	
Storts, Doug	(918) 495-2710	pds@willifordenergy.com	
Quint, Craig		craig.quint@state.co.us	
Sanchez, Chris		chris.sanchez@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476172	LOCATION	AC	05/11/2020		-	Rhoades Unit Gas Injection Flowline 3213S48W	AC

General Comment:

Flowline integrity inspection
 No signage at entrance.
 Stained ground around compressor equipment. Drums, buckets and jugs with no secondary containment.
 Contaminated material from spill being stored on location.
 No Form 12 or Form 44 found in database for compressor.

LocationOverall Good: ☐

Signs/Marker:			
Type	OTHER		
Comment:	No signage at entrance of location.		
Corrective Action:	Install signage to comply with Rule 605	Date:	03/31/2025

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

Spills:				
Type	Area	Volume		
Comment:	Stained ground around compressor equipment.			
Corrective Action:	In accordance with Rule 912.a.(2) Operator will investigate, cleanup, and document impacts resulting from Spill and Releases as soon as the impacts are discovered. Contact the area Environmental Protection Specialist Chris Sanchez			Date: 02/11/2025

In Containment: No

Comment: Contaminated material from spill being stored on location.

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Compressor	#		
Comment:			
Corrective Action:		Date:	

Venting:		
Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:		
Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>476172</u>	Type:	<u>LOCATION</u>	API Number:	<u>-</u>	Status:	<u>AC</u>	Insp. Status:	<u>AC</u>
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention	Fail	Chemical and oil containers w/o 2ndary containment

Comment:

Drums, buckets and jugs with no secondary containment.

Corrective Action:

Store containers in adequate secondary containment.

Date: 03/10/2025

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701104144	Flowline integrity inspection 701104143 photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6910166