


**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3677 From entrance to location**



**Photo # 3678 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3679 Location**



**Photo # 3680 Location**





**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3681 Location**



**Photo # 3682 Location**

**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3683 Location**



**Photo # 3684 Battery lacks required signage/not in compliance with CECMC rules**



**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3685 Rupture disc vent line does not comply with CECMC pressure safety device rules**



**Photo # 3686 Rupture disc vent line does not comply with CECMC pressure safety device rules**

**Inspection/Audit Photos**  
**Location Name: QB Energy KRK 7-15 (07E)**  
**Location #: 334858**



**Photo # 3687 Improperly marked deadman**



**Photo # 3688 Same improperly marked deadman**