

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4499 Entrance to location

Photo # 4498 Location

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4500 Location



Photo # 4510 Location

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4519 Location



Photo # 4553 NE corner of location

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 04556 SE corner of location



Photo # 4557 SW corner of location

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4558 NW corner of location



Photo # 4546 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4547 Open ended piping/wildlife hazard/available for entry by wildlife



Photo # 4549 Open ended piping/wildlife hazard/available for entry by wildlife

Inspection/Audit Photos

Location: QB ENERGY PRATHER/LATHAM-68S96W/3NWN (SOUTH GRAND VALLEY PAD - 3 B)

Location ID: 334183

Date: 2/10/2025



Photo # 4520 Signs at tank battery lack required information/do not comply with CECMC

Photo # 4532 Label showing signs of disrepair