

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4829 Entrance to location




Photo # 4844 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4830 Location



Photo # 4841 Location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4877 NW corner of location



Photo # 4878 SW corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4879 SE corner of location



Photo # 4880 NE corner of location

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



**Photo # 4853 Open ended piping/wildlife hazard/available for entry by wildlife**



**Photo # 4850 Open ended load line**

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4855 Open ended load line




Photo # 4856 Open ended load line

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



Photo # 4863 Open ended load line



Photo # 4865 Hole in secondary containment liner/liner needs maintenance

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



**Photo # 4867 Hole in secondary containment liner/liner needs maintenance**



**Photo # 4870 Holes in secondary containment liner/liner needs maintenance**

## Inspection/Audit Photos

Location: TEP ROCKY MOUNTAIN LLC FEDERAL-67S96W/11SWNE (GM 32-11 PAD)

Location ID: 334969

Date: 02/11/2025



**Photo # 4871 Hole in secondary containment liner/liner needs maintenance**



**Photo # 4873 Hole in secondary containment liner/liner needs maintenance**