

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/11/2025

Submitted Date:

02/11/2025

Document Number:

697010960**FIELD INSPECTION FORM**Loc ID 318592 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
241682	WELL	TA	09/01/2019	GW	123-09471	Dinner Lois Unit 2	TA

General Comment:

This is a routine audit. Any corrective actions from previous audits that have not been addressed are still applicable. There were no operator personnel on location at the time of this field audit.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign is not posted at well, see attached photo.		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	04/15/2025

Emergency Contact Number:

Comment:		Date: _____
Corrective Action:		

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	241682	Type:	WELL	API Number:	123-09471	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: <input type="text" value="Form 6A #403118488"/>									
Corrective Action: <input type="text"/> Date: _____									

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
<p>ECMC Audit Report Summary</p> <p>On Tuesday 2/11/2025 at approximately 14:00 hours, I, Inspector Tom Peterson, conducted an on-site inspection at the Noble Energy Dinner Lois Unit #2 location #318592 in Weld County, Colorado.</p> <p>While there, I observed that the wellhead sign was not posted. During this inspection the following possible compliance issues were observed: Rule 605.d. with a corrective action date of 4/15/2025. A follow up inspection on this site needs to be conducted to ensure the compliance issues have been corrected to comply with ECMC rules.</p> <p>This is a summary of the inspection report.</p>	petersont	02/11/2025

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404089853	INSPECTION SUBMITTED	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6914415
697010961	Photo	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6914374