

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
403980311

Date Received:
02/20/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:
Name:
Phone: () Fax: ()
Email:

Additional Operator Contact:

Contact Name	Phone	Email
TEP		COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302854
Inspection Date: 10/03/2024 FIR Submit Date: 10/03/2024 FIR Status:

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850
Address: 1058 COUNTY ROAD 215
City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 334812

Location Name: FEDERAL-67S96W Number: 3NESW County:
Qtrqtr: NESW Sec: 3 Twp: 7S Range: 96W Meridian: 6
Latitude: 39.465209 Longitude: -108.096636

FACILITY - API Number: 05-045-00 Facility ID: 334812

Facility Name: FEDERAL-67S96W Number: 3NESW
Qtrqtr: NESW Sec: 3 Twp: 7S Range: 96W Meridian: 6
Latitude: 39.465209 Longitude: -108.096636

CORRECTIVE ACTIONS:

1 CA# 199297

Corrective Action: Secure equipment to comply with Rule 608.e. Date: 10/10/2024

Response: CA COMPLETED Date of Completion: 10/17/2024

Operator Comment: Separator lines have been plugged. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

2 CA# 199298

Corrective Action: Install sign to comply with Rule 605.d.

Date: 11/02/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Wellhead signs have been replaced. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

3 CA# 199299

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 10/18/2024

Response: CA COMPLETED

Date of Completion: 10/17/2024

Operator Comment: Location and access road have been bladed/graded to repair rills and increase stabilization. Check dams have been maintained. Corrective Action complete.

ECMC Decision:

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA #199297: Separator lines have been plugged. Corrective Action complete.
CA #199298: Wellhead signs have been replaced. Corrective Action complete.
CA #199299: Location and access road have been bladed/graded to repair rills and increase stabilization. Check dams have been maintained. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/20/2025 8:58:47 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

Document Number	Description

Total Attach: 0 Files