

# State of Colorado Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
404013615

Date Received:  
02/21/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>TEP</u>		<u>COGCCInspectionReports@terraep.com</u>

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708302958  
Inspection Date: 10/23/2024 FIR Submit Date: 10/24/2024 FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC Company Number: 96850  
Address: 1058 COUNTY ROAD 215  
City: PARACHUTE State: CO Zip: 81635

**LOCATION** - Location ID: 324239

Location Name: GM-66S96W Number: 27SWSE County: \_\_\_\_\_  
Qtrqtr: SWSE Sec: 27 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.490788 Longitude: -108.092266

**FACILITY** - API Number: 05-045-00 Facility ID: 324239

Facility Name: GM-66S96W Number: 27SWSE  
Qtrqtr: SWSE Sec: 27 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.490788 Longitude: -108.092266

**CORRECTIVE ACTIONS:**

**1** CA# 200034

Corrective Action: Comply with CECMC General Safety rules. Date: 10/30/2024

Response: CA COMPLETED Date of Completion: 11/21/2024

Operator Comment: Ramp installed in cellar for wildlife egress. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 200035

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/09/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator  
Comment:

Location and access road have been bladed/graded to increase stabilization. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: CA #200034: Ramp installed in cellar for wildlife egress. Corrective Action complete.  
CA #200035: Location and access road have been bladed/graded to increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 2/21/2025 5:24:04 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404013615	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files