

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/04/2025

Submitted Date:

03/05/2025

Document Number:

713601935

FIELD INSPECTION FORMLoc ID 321147 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

5 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
HAHN, MIKE		mhahn@xeogc.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
206151	WELL	PR	08/01/2012	GW	009-06567	COOK 2-7	RI

General Comment:

This is a location inspection at the COOK #2-7 wellsite.
See attached photos and additional details within this report.

LocationOverall Good: ☐

Signs/Marker:			
Type			
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Sign at the tank battery should be placed in the front where it is visible from the County Road.

Corrective Action: Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	The door of the meter shed has fallen off.		
Corrective Action:	Maintain in good mechanical condition per Rule 608.e.	Date:	03/26/2025

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1		Open Top		,
Comment:	The netting on the open top tank is not maintained to prevent wildlife entry.				
Corrective Action:	Install or repair wildlife protection equipment. Comply with Rule 608.a.(13)				Date: 03/12/2025

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient		Inadequate
Comment:	There is insufficient secondary containment to prevent a spill. The berm is wore down and degraded.			
Corrective Action:	Repair or install berms or other secondary containment devices.			Date: 04/05/2025

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713601936	Inspection Photos	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6945599