

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404125597

Date Received:

03/12/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

General

sjninspections@ikavenergy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714001708

Inspection Date: 01/13/2025

FIR Submit Date: 01/21/2025

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 326272

Location Name: RICHARDSON GU E-N35N8W Number: 35SWNW County: _____

Qtrqtr: SWN Sec: 35 Twp: 35N Range: 8W Meridian: N

Latitude: 37.261516 Longitude: -107.719325

FACILITY - API Number: 05-067- -00 Facility ID: 326272

Facility Name: RICHARDSON GU E-N35N8W Number: 35SWNW

Qtrqtr: SWN Sec: 35 Twp: 35N Range: 8W Meridian: N

Latitude: 37.261516 Longitude: -107.719325

CORRECTIVE ACTIONS:

1 CA# 201931

Corrective Action: Stormwater controls (ie: BMPs) and erosion controls are needed on revegetating soils until the location is stabilized with desirable perennial vegetation. Additional seeding/reclamation efforts are needed on the location cutslopes.

Date: _____

Long term stabilization is needed along access road.

Response: CA COMPLETED

Date of Completion: 03/11/2025

Erosion on access road repaired and cut slope seeded

Corrective actions completed.

Print Name: Cross, Bruce Signed: _____

Signed:

Date: 3/12/2025 7:01:04 PM

10 website: <http://eprints.>

Total Attach: 2 Files