

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/25/2025

Submitted Date:

03/13/2025

Document Number:

717100116**FIELD INSPECTION FORM**Loc ID 458732 Inspector Name: Rollins, Grace On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1099 18TH STREET SUITE 1500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Anderson, Laurel		laurel.anderson@state.co.us	
PDC, Legacy		rbucogccinspectionreports@c hevron.com	All Legacy PDC Inspections
Metz, Collin		collin.metz@state.co.us	
Graber, Nikki		nikki.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
489186	SPILL OR RELEASE	AC	02/03/2025		-	Elkhead	EI

General Comment:**ECMC Environmental Field Inspection Report Summary**

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 489186

Spill Name: Elkhead

Facility ID: 458732

Reported Date of Discovery: 01/28/2025

Date of Inspection: 02/25/2025

Current site status:

-A small area appears to have been excavated at the spill location since the Initial Spill/Release report (Form 19 Document Number 404075009; 01/30/2025).

-An excavation remains open at the spill location.

-Orange construction fencing surrounds the excavation.

-Pink flags are visible in an area of impacted vegetation and soil at the spill location.

-No BMPs in place to control stormwater runoff from the spill area.

-Multiple plastic bags that appear to have been used for soil screening/sampling are visible in and around the spill area. These bags are also visible in the photo documentation provided with the Initial Spill/Release report (Form 19 Document Number 404075009) and appear to have been left on location since the waste characterization sampling was conducted on 01/29/2025 (27 days ago, as of the inspection on 02/25/2025).

See attached corrective actions.

Location				
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date: _____
Corrective Action:				
Good Housekeeping:				
Type	TRASH			
Comment:	Multiple plastic bags that appear to have been used for soil screening/sampling are visible in and around the spill area. These bags are also visible in the photo documentation provided with the Initial Spill/Release report (Form 19 Document Number 404075009) and appear to have been left on location since the waste characterization sampling was conducted on 01/29/2025 (27 days ago, as of the inspection on 02/25/2025).			
Corrective Action:	Comply with Rule 606. CA due date backlisted to the date the plastic bags appear to have been left on location.			Date: 01/29/2025
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Venting:				
Yes/No				
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Location Construction

Location ID: 489186 CDP: _____

Comment: _____

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment: _____

Corrective Action: _____

Date: _____

Wildlife BMPs:

Comment: _____

Corrective Action: _____

Date: _____

Comment: No BMPs in place to control stormwater runoff from the spill area.

Corrective Action: Install BMPs in accordance with 1002.f.(2) to prevent runoff and completely contain impacts around the spill footprint.

Date: 03/27/2025

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____

Address: _____

Phone Number: _____

Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____

Phone Number: _____

Date Onsite Request Received: _____

Date of Rule 306 Consultation: _____

Request LGD Attendance: _____

LGD Contact Information:

Name: _____

Phone Number: _____

Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities									
Facility ID:	489186	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment:

A small area appears to have been excavated at the spill location since the Initial Spill/Release report (Form 19 Document Number 404075009; 01/30/2025). An excavation remains open at the spill location. Pink flags are visible in an area of impacted vegetation and soil at the spill location. A stormwater drainage is located immediately adjacent to the spill area. Multiple plastic bags that appear to have been used for soil screening/sampling are visible in the spill area. A Form 19 Supplemental Report which requests closure of Spill ID 489186 is due by 04/28/2025.

Corrective Action:

Operator will provide notice to ECMC DJ Basin Environmental Supervisor Nikki Graber and to ECMC Area EPS via email at least 48 hours prior to any sampling events performed on location.

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100117	ECMC Photo Log - Elkhead	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6957795