

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/11/2025

Submitted Date:

03/20/2025

Document Number:

711902124

FIELD INSPECTION FORMLoc ID 316940 Inspector Name: SCHURE, KYM On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

ECMC Operator Number: 31257

Name of Operator: FRITZLER RESOURCES INC

Address: P O BOX 114

City: FORT MORGAN State: CO Zip: 80701

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		gfritzler@bresnan.net	
Heibel, Krystal		krystal.heibel@state.co.us	
Waggoner, Kyle		kyle.waggoner@state.co.us	
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
233352	WELL	PR	10/01/2021	OW	121-05388	BEN 1	PR

General Comment:

ROUTINE FIR - CA'S WITH DATES CITED IN THE FIR - READ COMPLETELY AND PERFORM CORRECTIVE ACTIONS

CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES WITH PW PIT FREEBOARD AND SOILS AT WELLHEAD

PHOTOS ATTACHED FOR REVIEW

Location

Lease Road:			
Type	Access		
comment:	TWO TRACK ACROSS GRASSLAND - MAINTAIN LEASE ROAD - FILL RUTS		
Corrective ActionL		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:	OPERATOR SIGN - SATISFACTORY		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	SATISFACTORY		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	INADEQUATE PLACARDING ON TANKS AT BATTERY		
Corrective Action:	INSTALL PLACARDING/SIGN TO COMPLY WITH RULE 605 SERIES (605.h.)	Date:	05/20/2025

Emergency Contact Number:

Comment:	SATISFACTORY	Date:	
Corrective Action:		Date:	

Good Housekeeping:			
Type	DEBRIS		
Comment:	DEBRIS ON GROUND AT SOUTH END OF PW PIT #2 See photograph attached		
Corrective Action:	COMPLY WITH RULE 606	Date:	04/04/2025
Type	STORAGE OF SUPL		
Comment:	TUBING ON GROUND AT PJ		
Corrective Action:	COMPLY WITH RULE 606	Date:	04/04/2025

Overall Good: ☐

Spills:				
Type	Area	Volume		
Crude Oil	WELLHEAD			
Comment:	SOIL AFFECTED BY CO - COVERED BY DIRT - REMEDIATE/REMOVE CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES			
Corrective Action:	PROPERLY DISPOSE OR TREAT IN ACCORDANCE WITH RULE905.f. (48) hrs. to perform clean-up CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES			Date: 03/22/2025

In Containment: Yes

Comment: SOILS AT WELLHEAD - SEE PHOTOGRAPHES - PREVIOUS UNREPORTED SPILL EVIDENCED ON
CEMENT PAD AND COVERED BY DIRT. SEE PHOTO

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS

CRUDE OIL	2	STEEL AST			
Comment: INSTALL PLACARDING ON TANKS AT BATTERY					
Corrective Action: COMPLY WITH RULE 600 SERIES					Date: 05/20/2025
Paint					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: RECONSTRUCT/REPAIR BERMS AT TANK BATTERY					
Corrective Action: REPAIR OR INSTALL BERMS PER RULE 912.d(1)					Date: 04/09/2025
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	233352	Type:	WELL	API Number:	121-05388	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	CA's are cited within the FIR - Read completely and comply with appropriate Rules and CA dates.								
Corrective Action:								Date:	
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

Environmental**Spills/Releases:**

Type of Spill: OIL _____

Estimated Spill Volume: _____

 Comment: **PREVIOUS UNREPORTED RELEASE/SPILL AT WELLHEAD - COVERED BY DIRT -
 REMEDIATE/REMOVE CONTACT ECMC ENVIRONMENTAL GROUP FOR DIRECTIVES**

 Corrective Action: **COMPLY WITH RULE 905.f, (48) hrs. to perform clean-up - Contact ECMC Environmental
 Group for directives.**

Date: 03/22/2025

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____

Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

ECMC Comments

Comment	User	Date
CA's and dates are cited within this FIR - Contact ECMC Environmental Group for directives. Complete CA's with cited dates per Rule.	schureky	03/20/2025
Photographs attached		

Attached DocumentsYou can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
711902143	Location photographs	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6967963