

Birds of Prey 36-10-61

Location 420207

Field Inspection Document No. 696307204

Corrective Action	Repair or install berms or other secondary containment devices per Rule 603.o.
Operator Response	Berms have been repaired. All animal burrows have been filled in.



Birds of Prey 36-10-61

Location 420207

Field Inspection Document No. 696307204

