

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404144154

Date Received:
03/27/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 4 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10456
Name of Operator: CAERUS PICEANCE LLC
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
.		ecmc.inspections@qb-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718100327
Inspection Date: 03/17/2025 FIR Submit Date: 03/21/2025 FIR Status: _____

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC Company Number: 10456
Address: 1001 17TH STREET #1600
City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 425805

Location Name: NPR Number: H15-596 County: _____
Qtrqtr: SENE Sec: 15 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.616619 Longitude: -108.146697

FACILITY - API Number: 05-045-00 Facility ID: 425805

Facility Name: NPR Number: H15-596
Qtrqtr: SENE Sec: 15 Twp: 5S Range: 96W Meridian: 6
Latitude: 39.616619 Longitude: -108.146697

CORRECTIVE ACTIONS:

1 CA# 203557

Corrective Action: Maintain BMP to ensure control measure remains in proper functioning condition, and is sufficiently impervious to contain a spill or release. Date: 04/21/2025

Response: CA COMPLETED Date of Completion: 03/27/2025

Operator Comment: Replaced secondary containment perimeter and repaired compromised liner to provide sufficiently impervious BMP on containment.

ECMC Decision: _____

ECMC Representative:

3 CA# 203559

Corrective Action: Comply with Rule 1003.a

Date: 04/21/2025

Response: CA COMPLETED

Date of Completion: 03/26/2025

Operator Comment: Backfilled all rat holes on location to comply with ECMC rule 1003.a.

ECMC Decision:

ECMC Representative:

4 CA# 203560

Corrective Action: Conduct work to address the subsidence issues occurring on the Location, and to ensure site remains stabilized

Date: 04/21/2025

Response: CA COMPLETED

Date of Completion: 03/26/2025

Operator Comment: Addressed lack of soil stabilization within recent P&A area. Will continue to monitor.

ECMC Decision:

ECMC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Joseph Gracey

Signed:

Title: Compliance

Date: 3/27/2025 4:18:03 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (http://ecmcweblink.state.co.us/) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404144154	FIR RESOLUTION SUBMITTED
404144165	Pad Surface 1
404144166	Pad Surface 2
404144167	Pad Surface 3
404144169	Tank Containment
404144170	Rat Hole
404144171	Rat/Mouse Hole

Total Attach: 7 Files