

Inspection Photos

Location Name: QB Energy SCARBER 2-42 (RN2) Pad

Location #: 334668



Mar 31, 2025 at 1:06:47 PM



Mar 31, 2025 at 1:08:43 PM

Photo # 8482 From Entrance to location

Photo # 8483 Location

Inspection Photos
Location Name: QB Energy SCARBER 2-42 (RN2) Pad
Location #: 334668



Photo # 8484 Location



Photo # 8485 Location

Inspection Photos
Location Name: QB Energy SCARBER 2-42 (RN2) Pad
Location #: 334668

Mar 31, 2025 at 1:07:45 PM



Photo # 8486 Location

Mar 31, 2025 at 1:12:55 PM



Photo # 8487 Location

Inspection Photos
Location Name: QB Energy SCARBER 2-42 (RN2) Pad
Location #: 334668



Photo # 8488 PRV vent line does not comply with CECMC pressure safety device rules

Photo # 8489 PRV vent line does not comply with CECMC pressure safety device rules

Inspection Photos
Location Name: QB Energy SCARBER 2-42 (RN2) Pad
Location #: 334668



Photo # 8490 Sign at entrance to location obscured by weeds