

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2025

Submitted Date:

04/02/2025

Document Number:

717100131**FIELD INSPECTION FORM**Loc ID _____ Inspector Name: _____ On-Site Inspection ☐
Rollins, Grace 2A Doc Num: _____**Operator Information:**ECMC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		ECMCInspections@Oxy.com	All Inspections
Graber, Nikki		nikki.graber@state.co.us	
Robinson, Taylor		taylor.robinson@state.co.us	
Mickelson, Erik		Erik_Mickelson@oxy.com	Oxy Environmental
Kiel, Macy	970-515-1110	Macy_Kiel@oxy.com	Staff Environmental Engineer

General Comment:[ECMC Environmental Field Inspection Report Summary](#)

Any corrective actions from previous inspections, NOAVs and/or conditions of approval from previous forms that have not been fully addressed are still applicable. There were no operator or contract environmental personnel on location at the time of this field inspection. Photos attached to document site conditions.

Spill ID: 486756

Spill Name: Iceman State 32N-A16HZ

Facility ID: 481351

Reported Date of Discovery: 04/23/2024

Date of Inspection: 03/26/2025

Current site status:

-Excavation has been backfilled.

-No environmental impacts were visible.

-Separator has been removed from the Spill area.

-The most recent Form 19 (Doc. # 403947642) was submitted on 10/07/2024; the Operator's request for closure of Spill ID 486756 was removed at the time of form approval by ECMC on 11/15/2024.

See attached corrective actions. A Supplemental Form 19 is required.

Environmental

Spills/Releases:

Type of Spill:Estimated Spill Volume:

Comment:Spill ID 486756 was created to address the remediation of impacts identified at the Iceman State 32N-A16HZ facility. The excavation has been backfilled. No environmental impacts were visible. The most recent Form 19 (Doc. # Doc. # 403947642) was submitted on 10/07/2024; the Operator's request for closure of Spill ID 486756 was removed at the time of approval by ECMC on 11/15/2024.

Corrective Action:In accordance with Rule 912.b.(6), Operator shall provide an updated Form 19 – Supplemental requesting closure of Spill ID 486756. If the remediation required by the COA on Form 19 Doc. # 403947642 has not been completed, Operator shall also provide a Form 27 – Initial for the ongoing remediation.

Date:04/18/2025

Reportable:GPS: LatLong

Proximity to Surface Water:Depth to Ground Water:

Water Well Complaint:

DWR Receipt Num:Owner Name:GPS :LatLong

Field Parameters:

Sample Location:Comment:

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
717100132	ECMC Photo Log_Iceman State 32N-A16HZ	https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6990560

Date Run: 4/4/2025 Doc [#717100131]

Page 2 of 2