

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404106392

Date Received:

04/09/2025

## FIR RESOLUTION FORM

**Overall Status:**

**CA Summary:**

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

**Additional Operator Contact:**

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

**ECMC INSPECTION SUMMARY:**

FIR Document Number: 708302949

Inspection Date: 10/22/2024

FIR Submit Date: 10/22/2024

FIR Status: \_\_\_\_\_

**Inspected Operator Information:**

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

**LOCATION - Location ID: 335388**

Location Name: GM-66S96W Number: 23SWSW County: \_\_\_\_\_

Qtrqtr: SWS Sec: 23 Twp: 6S Range: 96W Meridian: 6  
W

Latitude: 39.502078 Longitude: -108.084706

**FACILITY - API Number: 05-045- -00 Facility ID: 335388**

Facility Name: GM-66S96W Number: 23SWSW

Qtrqtr: SWS Sec: 23 Twp: 6S Range: 96W Meridian: 6  
W

Latitude: 39.502078 Longitude: -108.084706

**CORRECTIVE ACTIONS:**

1 CA# 199937

Corrective Action: Secure equipment to comply with Rule 608.e.

Date: 10/30/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator  
Comment:

Lines on separator have been plugged. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC Representative:	
----------------------	--

<b>2</b>	CA# 199938	
Corrective Action:	Secure equipment to comply with Rule 608.e.	Date: 10/20/2024
Response:	CA COMPLETED	Date of Completion: 11/21/2024
Operator Comment:	Secured bird protectors on separators. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

<b>3</b>	CA# 199939	
Corrective Action:	Protect or remove soil stockpile from location. 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.	Date: 03/25/2024
Response:	CA COMPLETED	Date of Completion: 02/26/2025
Operator Comment:	Stockpile has been removed. Corrective Action complete.	
ECMC Decision:		
ECMC Representative:		

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA #199937: Lines on separator have been plugged. Corrective Action complete. CA #199938: Secured bird protectors on separators. Corrective Action complete. CA #199939: Stockpile has been removed. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 4/9/2025 11:39:54 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404106392	FIR RESOLUTION SUBMITTED

Total Attach: 1 Files