

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404107458

Date Received:

04/09/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 708303502

Inspection Date: 02/21/2025

FIR Submit Date: 02/25/2025

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 428684

Location Name: PUCKETT/TOSCO Number: PA 443-34 County: \_\_\_\_\_

Qtrqtr: NESE Sec: 34 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479189 Longitude: -107.978760

### FACILITY - API Number: 05-045-00 Facility ID: 428684

Facility Name: PUCKETT/TOSCO Number: PA 443-34

Qtrqtr: NESE Sec: 34 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479189 Longitude: -107.978760

### CORRECTIVE ACTIONS:

1 CA# 202699

Corrective Action: Install label to comply with Rule 605.h.

Date: 03/28/2025

Response: CA COMPLETED

Date of Completion: 02/26/2025

Operator Comment: Produced water tank sticker has been replaced. Corrective Action complete.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

2 CA# 202700

Corrective Action: 1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 03/13/2025

Response: CA COMPLETED

Date of Completion: 03/10/2025

Operator Comment: Location and access road have been bladed/graded. 1 1/2" screened rock was added to the location to increase stabilization. Corrective Action complete.

ECMC Decision:

ECMC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: CA #202699: Produced water tank sticker has been replaced. Corrective Action complete.  
CA #202700: Location and access road have been bladed/graded. 1 1/2" screened rock was added to the location to increase stabilization. Corrective Action complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jordan Veith

Signed:

Title: TEP Representative

Date: 4/9/2025 12:26:54 PM

#### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
-----------------	-------------

--	--

Total Attach: 0 Files