

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:

404107697

Date Received:

04/09/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

4 of 4 CAs from the FIR responded to on this Form

4 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 708302947

Inspection Date: 10/22/2024

FIR Submit Date: 10/22/2024

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 323787

Location Name: ExxonMobil Number: MV 10-23 County: _____

Qtrqtr: NWS Sec: 23 Twp: 6S Range: 96W Meridian: 6
W

Latitude: 39.506308 Longitude: -108.083283

FACILITY - API Number: 05-045-00 Facility ID: 323787

Facility Name: ExxonMobil Number: MV 10-23

Qtrqtr: NWS Sec: 23 Twp: 6S Range: 96W Meridian: 6
W

Latitude: 39.506308 Longitude: -108.083283

CORRECTIVE ACTIONS:

1 CA# 199933

Corrective Action: Remove stored supplies from location.

Date: 10/29/2024

Response: CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment: Supplies have been removed from location. Corrective Action complete.

ECMC Decision: _____

ECMC Representative:		
----------------------	--	--

2

CA# 199934

Corrective Action:

Secure equipment to comply with Rule 608.e.

Date: 10/28/2024

Response:

CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment:

Open ended lines have been plugged. Corrective Action complete.

ECMC Decision:

ECMC Representative:

3

CA# 199935

Corrective Action:

Secure equipment to comply with Rule 608.e.

Date: 10/28/2024

Response:

CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment:

Separator hatches have been secured. Corrective Action complete.

ECMC Decision:

ECMC Representative:

4

CA# 199936

Corrective Action:

1002.f.(2): Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations to control Stormwater runoff in a manner that minimizes erosion, transport of sediment offsite, and site degradation. BMPs shall be maintained until the facility is abandoned and final reclamation is achieved pursuant to Rule 1004.

Date: 11/07/2024

Response:

CA COMPLETED

Date of Completion: 11/21/2024

Operator Comment:

Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.

ECMC Decision:

ECMC Representative:

<u>OPERATOR COMMENT AND SUBMITTAL</u>	
Comment:	CA #199933: Supplies have been removed from location. Corrective Action complete. CA #199934: Open ended lines have been plugged. Corrective Action complete. CA #199935: Separator hatches have been secured. Corrective Action complete. CA #199936: Location and access road have been bladed/graded to remove rutting and increase stabilization. Corrective Action complete.
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Jordan Veith	Signed: _____
Title: TEP Representative	Date: 4/9/2025 1:23:13 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>

Total Attach: 0 Files