

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404160281

Date Received:

04/10/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10633

Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLC

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Luke Kelly

970-939-6353

lkelly@civiresources.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 718600336

Inspection Date: 02/27/2025

FIR Submit Date: 03/05/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: CRESTONE PEAK RESOURCES OPERATING LLC

Company Number: 10633

Address: 555 17TH STREET SUITE 3700

City: DENVER State: CO Zip: 80202

#### LOCATION - Location ID: 305653

Location Name: WILLIAM H PELTIER 61N68W Number: 20SWNW County: \_\_\_\_\_

Qtrqtr: SWN Sec: 20 Twp: 1N Range: 68W Meridian: 6  
W

Latitude: 40.038640 Longitude: -105.035360

#### FACILITY - API Number: 05-123- -00 Facility ID: 305653

Facility Name: WILLIAM H PELTIER 61N68W Number: 20SWNW

Qtrqtr: SWN Sec: 20 Twp: 1N Range: 68W Meridian: 6  
W

Latitude: 40.038640 Longitude: -105.035360

### CORRECTIVE ACTIONS:

1 CA# 203004

Corrective Action: Comply with the reclamation rules to remove all debris, abandoned gathering line risers, and flowline risers, and equipment (regardless of ownership) within three months of plugging (09/13/2024) the associated facility.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/09/2025

Operator  
Comment:

Operator has removed the remaining equipment in order to comply with Rules 606 & 1004 .

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

**2** CA# 203005

Corrective Action: Comply with Rule 1002.f.2. Maintain stormwater BMPs and minimize erosion until site meets final reclamation standards.

Date: \_\_\_\_\_

Response: CA COMPLETED

Date of Completion: 04/09/2025

Operator  
Comment:

Operator has addressed the erosion issue, in order to comply with Rule 1002.f.2.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: CA follow-up has been completed for this location.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Aubrey Noonan

Signed: \_\_\_\_\_

Title: Sr Regulatory Analyst

Date: 4/10/2025 10:19:28 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404160281	FIR RESOLUTION SUBMITTED
404160292	Inspection Resolution

Total Attach: 2 Files