

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9646 From entrance to location



Photo # 9647 Location

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9648 Location



Photo # 9649 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017




Photo # 9650 Location



Photo # 9651 Location



Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9652 Location



Photo # 9653 Unmarked deadman

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9654 Same unmarked deadman



Photo # 9655 Same unmarked deadman from a different angle

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9656 Barbed wire fence needs maintenance/wildlife hazard & trip hazard



Photo # 9657 Barbed wire fence needs maintenance/wildlife hazard & trip hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9658 Barbed wire fence needs maintenance/wildlife hazard & trip hazard



Photo # 9659 Barbed wire fence needs maintenance/wildlife hazard & trip hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9660 Barbed wire fence needs maintenance/wildlife hazard & trip hazard



Photo # 9661 Barbed wire fence needs maintenance/wildlife hazard & trip hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9662 Barbed wire fence needs maintenance/wildlife hazard & trip hazard



Photo # 9663 Barbed wire fence needs maintenance/wildlife hazard & trip hazard

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9664 Barbed wire fence needs maintenance/wildlife hazard & trip hazard



Photo # 9665 Operator emergency # on methanol tank disconnected & not in service (additionally labeling with operator name is peeling & starting to become illegible)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017




Photo # 9666 Operator emergency # on methanol tank disconnected & not in service (additionally labeling with operator name is peeling & starting to become illegible)



Photo # 9667 Operator emergency # on methanol tank disconnected & not in service (additionally labeling with operator name is peeling & starting to become illegible)

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9668 Methanol tank



Photo # 9669 Operator emergency # on sign is disconnected
& not in service

Inspection/Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC NORTH BANK E Pad

Location ID: 336017



Photo # 9670 PRV vent line does not comply with CECMC pressure safety device rules or general safety rules



COLORADO
Energy & Carbon Management
Commission
Department of Natural Resources