

State of Colorado  
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:  
404163090

Date Received:  
04/14/2025

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 10560

Name of Operator: WEST TEXAS OPERATING CO LLC DBA XTREME  
ENERGYCO

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Mike Hahn

3615701600

mhahn@xecusa.com

### ECMC INSPECTION SUMMARY:

FIR Document Number: 713601935

Inspection Date: 03/04/2025

FIR Submit Date: 03/05/2025

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: WEST TEXAS OPERATING CO LLC DBA XTREME  
ENERGYCO

Company Number: 10560

Address: PO BOX 2326

City: VICTORIA State: TX Zip: 77902

#### LOCATION - Location ID: 321147

Location Name: COOK-633S43W Number: 7SESW County: BACA

Qtrqr: SESW Sec: 7 Twp: 33S Range: 43W Meridian: 6

Latitude: 37.181640 Longitude: -102.308727

#### FACILITY - API Number: 05-009-00 Facility ID: 206151

Facility Name: COOK Number: 2-7

Qtrqr: SESW Sec: 7 Twp: 33S Range: 43W Meridian: 6

Latitude: 37.181640 Longitude: -102.308727

### CORRECTIVE ACTIONS:

1 CA# 203006

Corrective Action: Repair or install berms or other secondary containment devices.

Date: 04/05/2025

Response: CA COMPLETED

Date of Completion: 04/04/2025

Operator Comment: Repaired

ECMC Decision: \_\_\_\_\_

Date: 4/14/2025 9:04:24 AM

## Page 2 of 2