

State of Colorado  
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404165231

Date Received:

04/15/2025

## FIR RESOLUTION FORM

**Overall Status:**

CA Summary:

1 of 3 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

ECMC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

Kellerby, Shaun

shaun.kellerby@state.co.us

Coleman, Chris

chris.coleman@state.co.us

### ECMC INSPECTION SUMMARY:

FIR Document Number: 718100399

Inspection Date: 04/06/2025

FIR Submit Date: 04/08/2025

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

### LOCATION - Location ID: 323868

Location Name: Juhan

Number: 14-26H

County: \_\_\_\_\_

Qtrqr: SESW Sec: 26 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.492247 Longitude: -107.859729

### FACILITY - API Number: 05-045-

-00

Facility ID: 323868

Facility Name: Juhan

Number: 14-26H

Qtrqr: SESW Sec: 26 Twp: 6S Range: 94W Meridian: 6

Latitude: 39.492247 Longitude: -107.859729

### CORRECTIVE ACTIONS:

1 CA# 203922

Corrective Action: Install or repair wildlife protection equipment.

Date: 04/18/2025

Response: CA COMPLETED

Date of Completion: 04/15/2025

Operator  
Comment:

ECMC Rule 1202.a.(4) requires installation of fencing, netting or other exclusion devices at " ... new drilling pits, production pits, and other pits associated with oil and gas operations that are intended to contain fluids." This knock-out tank / containment trough does not meet the definition of a "pit" per ECMC rules, and therefore ... fencing, netting, and other exclusion devices are not required for this ancillary tank that is already protected by

fencing and an earthen secondary containment structure. Please note that the knock-out tank sits inside a poly containment tub which is located inside a fenced secondary containment structure (see attached photo). Again, this knock-out tank does not meet the definition of a "pit" per ECMC rules, and therefore ... fencing, netting, and other exclusion devices are not required.

It has been TEP's experience that placing a net or wire mesh covering over such tanks / troughs has a detrimental affect upon wildlife. Birds and even small rodents are attracted to the rain water / snow melt that accumulates inside the trough. Once the birds / rodents get inside the covered trough, they often times cannot find their way back out and become trapped and succumb inside the trough. To prevent birds and rodents from becoming trapped inside the netted structures, TEP is removing any existing nets and mesh coverings from the chemical containment troughs. TEP will install escape ramps / boards to prevent any entrapment inside the trough. In addition, TEP is actively inspecting the containment structures to ensure that the chemical tanks are not leaking, and also to remove any fresh water that may be accumulating inside the containment. This corrective action has been addressed.

ECMC Decision: \_\_\_\_\_

ECMC  
Representative: \_\_\_\_\_

#### OPERATOR COMMENT AND SUBMITTAL

Comment: ECMC Rule 1202.a.(4) requires installation of fencing, netting or other exclusion devices at " ... new drilling pits, production pits, and other pits associated with oil and gas operations that are intended to contain fluids." This knock-out tank / containment trough does not meet the definition of a "pit" per ECMC rules, and therefore ... fencing, netting, and other exclusion devices are not required for this ancillary tank that is already protected by fencing and an earthen secondary containment structure. Please note that the knock-out tank sits inside a poly containment tub which is located inside a fenced secondary containment structure (see attached photo). Again, this knock-out tank does not meet the definition of a "pit" per ECMC rules, and therefore ... fencing, netting, and other exclusion devices are not required.

It has been TEP's experience that placing a net or wire mesh covering over such tanks / troughs has a detrimental affect upon wildlife. Birds and even small rodents are attracted to the rain water / snow melt that accumulates inside the trough. Once the birds / rodents get inside the covered trough, they often times cannot find their way back out and become trapped and succumb inside the trough. To prevent birds and rodents from becoming trapped inside the netted structures, TEP is removing any existing nets and mesh coverings from the chemical containment troughs. TEP will install escape ramps / boards to prevent any entrapment inside the trough. In addition, TEP is actively inspecting the containment structures to ensure that the chemical tanks are not leaking, and also to remove any fresh water that may be accumulating inside the containment. This corrective action has been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Environmental Lead

Date: 4/15/2025 11:40:58 AM

### ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404165231	FIR RESOLUTION SUBMITTED
404165303	Photo

Total Attach: 2 Files