

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESW

Location ID: 335294

Date: 4/9/2025



Location Overview – Photo #08036



Location – Photo #08038

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESW

Location ID: 335294

Date: 4/9/2025



Location – Photo #08037



Location – Photo #08040

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESW

Location ID: 335294

Date: 4/9/2025



Stored Supplies/Wildlife Entry Hazard – Photo #08042



Stored Supplies/Wildlife Entry Hazard – Photo #08045

Audit Photos

Location Name: TEP ROCKY MOUNTAIN LLC, GIBSON GULCH UNIT-66S91W/30NESW

Location ID: 335294

Date: 4/9/2025



Berm Liner Patch is Peeling – Photo #08053