

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/07/2025

Submitted Date:

04/10/2025

Document Number:

718700279**FIELD INSPECTION FORM**Loc ID 317129 Inspector Name: Edwardson, Dylan On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**ECMC Operator Number: 88370Name of Operator: TIMKA RESOURCES LTDAddress: 2077 BAYFRONT DRCity: WINDSOR State: CO Zip: 80550**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**9 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Jackson, Ben		ben.jackson@state.co.us	
PIVONKA, TIMOTHY	970-667-9861	timkaresources@hotmail.com	PRESIDENT

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
117730	PIT	AC			-	THEURER FARMS 22-28	RI
119604	PIT	AC			-	THEURER FARNS 22-28	RI
236630	WELL	PR	12/15/2014	OW	121-09121	THEURER FARMS 22-28	RI
317129	LOCATION	AC			-	THEURER FARMS-63N52W 28SEW	RI

**General Comment:**This is an Interim Reclamation and Stormwater Inspection for Location ID (317129).

**Location**Overall Good: ☐**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Tank labels/NFPA placards are not legible (e.g. peeling, faded, cracked, etc). Install sign to comply with Rule 605.g.		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		Date: _____
Corrective Action:		

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Other	#		
Comment:	Wildlife netting at secondary containment requires maintenance. Install or repair wildlife protection equipment per Rule 902.b.		
Corrective Action:		Date:	
Type: Pump Jack	#		
Comment:	Visible leaks observed at pump jack and wellhead.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes per Rule 1002.f.(2).D.		Date: 04/17/2025

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	117730	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	119604	Type:	PIT	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	236630	Type:	WELL	API Number:	121-09121	Status:	PR	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									
Facility ID:	317129	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	RI
The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12									

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_ In \_\_\_\_\_

Comment

Northwest guy line anchor requires maintenance.

Install proper guy line markers per Rule 1003.a.

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? \_\_\_\_\_ Subsidence over on drill pit? \_\_\_\_\_

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established In

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment The location is within cropland but reference crop areas are currently fallow. The location will remain in-process and will have to be inspected during the active crop growing season to make an accurate assessment of vegetative conditions to ensure compliance per Rule 1003 standards.

Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including stormwater and weed management. Operator shall submit a Form 4 Interim Reclamation Complete notice when the location meets Rule 1003 standards. ECMC may conduct inspections prior to receiving said notice to ensure compliance with Rule 1003.

Corrective Action  Date \_\_\_\_\_

Overall Interim Reclamation In Process

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment:

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

## VEGETATIVE COVER \_\_\_\_\_

Comment: Corrective Action: 

Date \_\_\_\_\_

Overall Final Reclamation

Well Release on Active Location ☐Multi-Well Location ☐**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: This location does not comply with Rule 1002.f. During this inspection, it was observed that sediment transport has occurred as result of unstabilized pit berms. Sediment transport will need to be removed and additional stormwater control measures/BMPS will need to be implemented in order to prevent further site degradation and sediment transport from the pit area.

Corrective Action: **Install or repair required BMPs per Rule 1002.f.(2)C.**

Date: 04/24/2025

**Pits:** ☐ NO SURFACE INDICATION OF PIT**ECMC Comments**

Comment	User	Date
Form 4 (doc #403107379) for Rule 909.j compliance status update is currently "In-Process".	edwardsond	04/10/2025

**Attached Documents**You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
404160782	INSPECTION SUBMITTED	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6998826">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6998826</a>
718700286	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6998817">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=6998817</a>