

State of Colorado
Energy & Carbon Management Commission



1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Document Number:
404170726

Date Received:
04/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 24500

Name of Operator: PADCO LLC

Address: 16508 ARMINTA STREET

City: VAN NUYS State: CA Zip: 91406

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Richmond, Dan

dan@dsrinc.net

BROTHERTON, ANDREA

abrotherton@136elcamino.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 718700228

Inspection Date: 03/25/2025

FIR Submit Date: 03/28/2025

FIR Status: _____

Inspected Operator Information:

Company Name: PADCO LLC

Company Number: 24500

Address: 16508 ARMINTA STREET

City: VAN NUYS State: CA Zip: 91406

LOCATION - Location ID: 317037

Location Name: FASSLER-62N53W Number: 32NENE County: _____

Qtrqr: NENE Sec: 32 Twp: 2N Range: 53W Meridian: 6

Latitude: 40.102865 Longitude: -103.323734

FACILITY - API Number: 05-121- -00 Facility ID: 317037

Facility Name: FASSLER-62N53W Number: 32NENE

Qtrqr: NENE Sec: 32 Twp: 2N Range: 53W Meridian: 6

Latitude: 40.102865 Longitude: -103.323734

CORRECTIVE ACTIONS:

3 CA# 203746

Corrective Action: Perform reclamation in accordance with Rule 1003. Reseed disturbance areas and establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Use a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Ensure erosion controls are implemented to stabilize the seeded soil, and continue to monitor and manage this site until the location meets Rule 1003 standards. Corrective action date is the date the location was observed out of compliance.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/17/2025

Disturbed areas have been seeded. Location will be monitored until location meets Rule 1003.

--

Date: 04/11/2025

Date of Completion: 04/17/2025

The pit walls have been stabilized and erosion controls have been installed.

Signed:

Date: 4/18/2025 3:53:57 PM

--	--

Page 2 of 2