

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
404170857

Date Received:
04/18/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 34105

Name of Operator: GILBERT-STEWART OPERATING LLC

Address: 1801 BROADWAY STE 200

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

GILBERT KENT L

303-478-8393

kgoil@msn.com

STEWART SCOTT

srs.gso@prodigy.net

ECMC INSPECTION SUMMARY:

FIR Document Number: 713602079

Inspection Date: 04/10/2025

FIR Submit Date: 04/15/2025

FIR Status: _____

Inspected Operator Information:

Company Name: GILBERT-STEWART OPERATING LLC

Company Number: 34105

Address: 1801 BROADWAY STE 200

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 321888

Location Name: YELTSIN-615S45W Number: 1SWSE County: CHEYENNE

Qtrqtr: SWSE Sec: 1 Twp: 15S Range: 45W Meridian: 6

Latitude: 38.770777 Longitude: -102.395106

FACILITY - API Number: 05-017- -00 Facility ID: 208366

Facility Name: YELTSIN Number: 1

Qtrqtr: SWSE Sec: 1 Twp: 15S Range: 45W Meridian: 6

Latitude: 38.770777 Longitude: -102.395106

CORRECTIVE ACTIONS:

2 CA# 204146

Corrective Action: Comply with Rule 902. Install or repair wildlife protection equipment.

Date: 04/18/2025

Response: CA COMPLETED

Date of Completion: 04/17/2025

Operator
Comment:

Substance in secondary containment was vac'd out and disposed of down the Miller disposal well.

ECMC Decision: _____

Operator Comment:	Pump jack is down for repair as the saddle bearing is getting replaced.
-------------------	---

ECMC Decision: _____

Comment:	Corrective Actions #2 and #3 are complete. Corrective Action #1 will be addressed in a subsequent FIRR.
----------	---

Signed:

Date: 4/18/2025 4:33:42 PM

<u>Document Number</u>	<u>Description</u>
404170857	FIR RESOLUTION SUBMITTED
404171017	photo of secondary containment with bird netting and no more residue

Page 2 of 2