

# COLORADO OIL & GAS CONSERVATION FIELD INSPECTION REPORT



C

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100		
API No. 05- 001 - 06506			LEASE NAME: Piland & Co "A" #1		
LOCATION: NESW 15-35-64W			OPERATOR: Summit Oil		
DATE: 8/7/96			INSPECTOR: LAR		
Insp. Type: HR	Insp. Status: DA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F	Viol.: <input checked="" type="radio"/> Y N	NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
<b>Well ID Signs</b> (Rule 210, 604.c(4))		
<b>Pits (Reserve/Production)</b> (Rule 902, 903, 904, 905)		
<b>Fences</b> (Rule 603.b.7, 604.C.(3), 1002.A)		
<b>Tank Battery Equipment</b> (Rule 603.b.3, 604)		
<b>Fire Walls/Berms/Dikes</b> (Rule 603.b.12, 604)		
<b>General Housekeeping</b> (Rule 603)		
<b>Spills (Oil/Water)</b> (Rule 907)		
<b>Bradenhead</b> (Rule 207.b)		
<b>Drilling Well/Workover</b> (Rule 317)		
<b>Surface Rehabilitation</b> (Rule 1002, 1003, 1004, 1103)	Well has been plugged and location restored except for 5' of drilling line	
<b>Miscellaneous</b>	Sticking out of ground	

<b>CORRECTIVE ACTION REQUIRED:</b> Finalize site restoration by removing drilling line	
Date Corrective Action Required By: 8/26/96	Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.