

AUG 27 1974



00417737

# OIL AND GAS CONSERVATION COMMISSION OF THE STATE OF COLORADO

File in duplicate for Patented and Federal lands.  
File in triplicate for State lands.

COLO.

5. LEASE DESIGNATION AND SERIAL NO.

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

Allen &amp; Schramm, Inc.

3. ADDRESS OF OPERATOR

960 Petroleum Club Building-Denver, Co. 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.  
See also space 17 below.)  
At surface

At proposed prod. zone

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Monaghan

9. WELL NO.

#2

10. FIELD AND POOL, OR WILDCAT

11. SEC., T., R., M., OR BLK. AND

SURVEY OR AREA

NW 1/4 NW 1/4 SW 1/4

Sec 8 3S 65 W

12. COUNTY OR PARISH

Adams

13. STATE

Colo.

16.

### Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

#### NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON

REPAIR WELL

CHANGE PLANS

(Other)

#### SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT

(Other)

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

Intent to Abandon as follows:

Pump cement plug from 8375' to 8323'. Mud hole to 1899'. Set cement plug from 1899' to 1515'. Fox Hills from 1564' to 1849'. Mud hole to bottom of surface casing at 185'. Set 15 sacks cement from 185' to 136', mud to 28', 10 sacks cement to surface. Cut off surface pipe and weld on plate.

DVR	
FJP	
HHM	✓
JAM	✓
JJD	✓
GCH	✓
CGM	

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

V.P.

DATE Aug. 26, 1974

(This space for Federal or State office use)

APPROVED BY

TITLE

DIRECTOR

OGCC COMM. CHIEF

DATE

SEP 4 1974

CONDITIONS OF APPROVAL, IF ANY: