

State of Colorado
Energy & Carbon Management Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

404175597

Date Received:

04/23/2025

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

ECMC Operator Number: 10840

Name of Operator: ABUNDANCE ENERGY SERVICES LLC

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

aprice@abundance-energy.com

sjbcompliance@abundance-energy.com

ECMC INSPECTION SUMMARY:

FIR Document Number: 714002070

Inspection Date: 04/08/2025

FIR Submit Date: 04/11/2025

FIR Status: _____

Inspected Operator Information:

Company Name: ABUNDANCE ENERGY SERVICES LLC

Company Number: 10840

Address: 2121 S COLUMBIA AVE SUITE 101

City: TULSA State: OK Zip: 74114

LOCATION - Location ID: 333602

Location Name: OLSON-SMITH UNIT-N33N8W Number: 8SESE County: _____

Qtrqtr: SESE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.114019 Longitude: -107.735344

FACILITY - API Number: 05-067-00 Facility ID: 333602

Facility Name: OLSON-SMITH UNIT-N33N8W Number: 8SESE

Qtrqtr: SESE Sec: 8 Twp: 33N Range: 8W Meridian: N

Latitude: 37.114019 Longitude: -107.735344

CORRECTIVE ACTIONS:

1 CA# 204009

Corrective Action: Comply with Rule 1004.a to remove (regardless of ownership) all debris, abandoned gathering line risers, flowline risers, and equipment within three months of plugging (5/9/2017) the associated facility.

Date: _____

Response: CA COMPLETED

Date of Completion: 04/15/2025

Operator Comment: Email correspondance between inspector and Abundance notified and explained, with annotated images, that the riser in question is part of a gathering system for currentlly producing, operated wells and is currently in use. Rule 1004.a states only abandoned items need to be removed and this riser is not abandoned. Abundance would be willing to demonstate to inspector or other ECMC staff that the riser is active. Please see attached e-mail

correspondance.

ECMC Decision: _____

ECMC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attachments for both Remedial Report and email correspondence.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jaime Pugh

Signed: _____

Title: Engineering Analyst

Date: 4/23/2025 9:57:17 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on ECMC website (<http://ecmcweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
404175597	FIR RESOLUTION SUBMITTED
404175610	Remedial Report
404175611	Email Correspondance

Total Attach: 3 Files