

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5238 From entrance to location




Photo # 5239 Location

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5240 Location



Photo # 5241 Location

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5242 Location



Photo # 5243 Location

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5244 Location



Photo # 5245 Location



Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5246 Location



Photo # 5247 Location

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428




Photo # 5248 Location




Photo # 5249 Location

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5250 PRV vent line does not comply with CECMC pressure safety device rules



Photo # 5251 PRV vent line does not comply with CECMC pressure safety device rules

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5252 Staining near tank battery



Photo # 5253 Staining near tank battery

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5254 Staining near tank battery



Photo # 5255 Staining near tank battery

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5256 Staining near tank battery



Photo # 5257 Staining near tank battery

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5258 Staining near tank battery



Photo # 5259 Staining near tank battery

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Apr 23, 2025 at 4:03:36 PM
CO



Apr 23, 2025 at 4:03:57 PM
CO

Photo # 5260 Staining near tank battery

Photo # 5261 Staining near tank battery

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5262 Staining in secondary containment



Photo # 5263 Staining in secondary containment

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428



Photo # 5264 Debris



Photo # 5265 Debris

Inspection/Audit Photos

Location Name: QB Energy Benjamin Federal 28-12B2 (K28NW) Pad

Location ID: 335428




Photo # 5266 No check valve on line connecting BH line to flowline Benjamin Federal 33-4B (K28NW) well



Photo # 5267 No check valve on line connecting BH line to flowline Benjamin Federal 33-4B (K28NW) well