

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/01/2025

Submitted Date:

05/05/2025

Document Number:

713602133

**FIELD INSPECTION FORM**Loc ID 483009 Inspector Name: COSTA, RYAN On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 10763

Name of Operator: BNL (ENTERPRISE) INC

Address: 6494 S QUEBEC ST

City: ENGLEWOOD State: CO Zip: 80111

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kondrat, Peter	970-759-5370	pkondrat@bluestarhelium.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
483009	LOCATION	AC			-	State 09 SWSE 3054	RI

**General Comment:**

This is a pre-construction inspection at the JACKSON #02 L4 3154 location.  
See all comments and attached photos for inspection observations.

**Location Construction**

Location ID: 483504 CDP: \_\_\_\_\_

**Comment:** The soil type of this area is predominately Chacuaco which consists of topsoil to at least 10 inches that will need to be salvaged. Per Operator topsoil plan, 12" x 12" test pits will be dug in the south and east corners of the wellpad. Photos will be submitted of the test pits via Form 4 prior to construction." It does not appear that the photos of the test pits have been provided.

**Corrective Action:** Comply with topsoil protection plan and submit photos of the soil test pits.

**Date:** 05/12/2025

**Form 2A COAs:**

**Comment:** A form 42 notice was submitted which had a construction start date of 4/30/2025. No construction had commenced as of 5/1/2025. A 48 hr notice prior to construction will need to be provided.

**Corrective Action:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**Wildlife BMPs:**

**Comment:** \_\_\_\_\_

**Corrective Action:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**Comment:** \_\_\_\_\_

**Corrective**

**Action:** \_\_\_\_\_

**Date:** \_\_\_\_\_

**On Site Inspection (305):**Surface Owner Contact Information:

Name: \_\_\_\_\_

Address: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Cell Phone: \_\_\_\_\_

Operator Rep. Contact Information:

Landman Name: \_\_\_\_\_

Phone Number: \_\_\_\_\_

Date Onsite Request Received: \_\_\_\_\_

Date of Rule 306 Consultation: \_\_\_\_\_

Request LGD Attendance: \_\_\_\_\_

LGD Contact Information:

Name: \_\_\_\_\_ Phone Number: \_\_\_\_\_ Agreed to Attend: \_\_\_\_\_

Summary of Landowner Issues:

\_\_\_\_\_

Summary of Operator Response to Landowner Issues:

\_\_\_\_\_

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

\_\_\_\_\_

**Attached Documents**

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
713602135	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7035422">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7035422</a>