

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/05/2025

Submitted Date:

05/05/2025

Document Number:

715501661

**FIELD INSPECTION FORM**Loc ID 312780 Inspector Name: Burchett, Kirby On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

ECMC Operator Number: 45898

Name of Operator: KAISER-FRANCIS OIL COMPANY

Address: P O BOX 21468

City: TULSA State: OK Zip: 74121

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

10 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Opfer, Christina	(918) 491-4468	christinao@kfoc.ner	
Wilson, Justin	(970) 878-3825	jrwilson@blm.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222380	WELL	PR	01/01/2024	GW	081-05372	FOX GOV 1-30	PR

**General Comment:****ECMC Inspection Report Summary**

On Monday, 05/05/2025, Inspector Kirby Burchett, was on location for a routine field inspection at Kaiser-Francis Oil Company on the Fox Gov 1-30 well, Location #312780, in Moffat County, Colorado.

This location is within or in close proximity to a Colorado Parks and Wildlife (CPW) District with High Priority, NSO, Density and Other Consultation Habitat regulations.

Any Corrective Actions from previous Inspections are still applicable.

While there during normal operations the following compliance issues were observed:

1. Debris
2. Incomplete well sign

Refer to Inspection Photos for observed compliance issues.

A follow up on this site inspection will be conducted to ensure all compliance issues have been corrected to comply with ECMC rules.

**Location**Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:	Sign missing required information		
Corrective Action:	When no associated Tank battery is present at the Oil and Gas Location, the following information is required on the Well sign: Name of the Operator; Telephone number at which the Operator can be reached at all times; Telephone number for local emergency services (911 where available); The public road used to access the Well; Well name(s) and API number(s); The legal location of the Well(s) including the quarter/quarter section.	Date:	06/05/2025
Type	OTHER		
Comment:	As Location Entrance signs are replaced: The Well name; The Commission's Location identification number (ID #); The Operator's telephone number where it may be reached at all times; and the Telephone number(s) for local emergency services (911 where available) will be required.		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: (405) 262-5511

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Random debris		
Corrective Action:	All excess materials, rubbish, supplies, trash, or other waste material will be properly contained until removed from the Oil and Gas Location. At no time will debris be placed or remain on the ground.	Date:	05/21/2025
Type	WEEDS		
Comment:	Maintain noxious weed control on all disturbed and reclaimed areas as a result of Oil & Gas activities including access roads.		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Pumping unit and wellhead Fence panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
------------------	-----	--	-----------------



Inspected Facilities									
Facility ID:	222380	Type:	WELL	API Number:	081-05372	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	February 2025 Production Report								
Corrective Action:				Date:					

The subreport 'InspWellFlowline' could not be found at the specified location \\10.14.12

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Comment:		Operator is responsible for maintaining Best Management Practices (BMPs) to control vehicle tracking and potential sediment discharges from operational roads, well pads, and other unpaved surfaces.				
Corrective Action:						Date: _____
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to ECMC Images (<https://ecmc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
715501662	Inspection Photos	<a href="https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036128">https://ecmc.state.co.us/weblink/DownloadDocumentPDF.aspx?DocumentId=7036128</a>